

Complaint Report of Findings

Department of Construction & Inspections Code Compliance Division 700 Fifth Ave Suite 1900 PO Box 34019 Seattle, WA 98124-4019

Website: seattle.gov/sdci
Office Location: 700 Fifth Avenue,
19th Floor of Seattle Municipal Tower

Phone: (206) 615-0808

TTY: (206) 233-7156

Complaint Location: 4732 BROOKLYN AVE NE SEATTLE, WA 98105

Record Number: 002868-23CP

Complaint Type: Housing

Complaint Outcome: Admin Closure

Resolution Date: Jun 06, 2023

Alleged Complaint Description: Window has been broken for 2 months. no repair plan from management.

Additional Information: HOUSING - RRIO REG: 001-0146094